
From: Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFFRE3]
Sent: 6/5/2015 7:49:00 AM
To: David Craymer (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=David09]
Subject: FW: Ash Pond ABC inspection 06/03/15
Attachments: 20150603110633181.pdf

fyi

From: Jeffrey R Marcell (Generation - 3)
Sent: Friday, June 05, 2015 7:41 AM
To: Michael J Winters (Generation - 34)
Cc: John Cima (Generation - 34); Jeffrey C Heffelman (Generation - 3); Kenneth Roller (Services - 6)
Subject: RE: Ash Pond ABC inspection 06/03/15

Attached.

No Discharge at C Pond. Standing water around weir and Southeastern edge of Pond C and into center of C Pond beginning to recede. Water level inside bottom of weir is below pipe.

There was some seeping and dripping inside C Pond discharge weir, above the "board", and in both corners. Standing water has lowered despite the rain but the dripping has increased.

Standing water behind sand-bags at 'A' and standing water at the toe of the slope in this area were slightly more than last inspection because of rainfall. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water. The NE end of A Pond is holding water in pathway created from matting/equipment activity, noticeable depression in this section from activity related to drilling.

No standing water behind sand-bags at 'B' pond.

Precipitation from 6/2 event was 1.33 with similar events earlier in the week. Rain continued 6/4 & morning of 6/5.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)